

AIRPLANES SERIES

JUNKERS F13

WITH WINTER SKI

EARLY PROO


48020




GENERAL INSTRUCTION

SCALE
1:48

- HIGHLY DETAILED PLASTIC MODEL KIT
- PHOTO-ETCHED PARTS INCLUDED
- CLEAR PLASTIC PARTS INCLUDED
- HATCHES CAN BE ASSEMBLED IN OPEN OR CLOSED POSITION
- ENGINE & INTERIOR COMPARTMENT ACCURATELY REPRESENTED IN THE MODEL
- DECAL SHEET FOR 3 VARIANTS



1 B-LATA "Condor", Lettische LV AG. Latvia, Early 1920's



VOLDDYMYR
BOOTH 2025

UWAGA

Przy stosowaniu kleju i farb wszystkie prace należy wykonywać w przewiewnym miejscu z dala od źródeł ognia.
Oddziel części od wlewków nożem lub innym ciętym narzędziem. Oczyszczaj lampę błyskową i wytnij punkty pilnikiem igłowym i papier ścierny.
Dla ułatwienia montażu każda część jest oznaczona numerem.
Po złożeniu zestawu mogą pozostać niewykorzystane części.

УВАГА

При використанні клею та фарб всі роботи проводити подалі від джерел вогню у приміщенні, що добре провітрюється.
Деталі відокремлювати від літників ножем або іншим ріжучим інструментом. Зачистити облой і місця зрізу за допомогою надфайлу та наждачного паперу. Будівництво моделі виконувати згідно зі схемою.
Для зручності побудови кожна деталь позначена номером.
Після складання можуть залишитися невикористані деталі.

CAUTION

When you use glue or paint, do not use near open flame, and use in well ventilated room. When you take parts off from the runner frame, use modeling scissors or cutter.
See the bottom of this column for the meaning of symbols.
Extra details can remain after assembling of the kit.



POWTOŹR DWA RAZY
MAKE 2x
2 TEILE FERTIGEN
EFFECTUER 2 PIECES
FARE DUE PEZZI
TEE 2 KPL
GÖR 2 ST.
КІПЬКІСТЬ РАЗІВ



NIE UŻYWAJ KLEJU
DO NOT CEMENT
NIGHT KLEBEN
NE PAS COLLER
NON INCOLLARE
EILIMAA
LIMMAE
НЕ КЛЕЙТИ



OPCJE
OPTIONAL
NACH BELIEBEN
FACULTATIF
FACOLTATIVO
VALINNANVARAINEN
VALBAR
ВАРІАНТИ



ZROBIĆ DZIURĘ
OPEN HOLE
OFFNEN
FAIRE UN TROU
FORO APERTO
AVAA REIKÄ
OPPIA HALET
ЗРОБИТИ ОТВІР



ODCIĄĆ
REMOVE
ENTFERNEN
RETIRER
SEPARARE
POISTA
AVLÄGSNA
ВІДПІЗАТИ









ZGINAĆ
BEND
BITTE BIEGEN
PLIER S'IL VOUS PLAÎT
PIEGARE
TAITA
BOCKA
ВІГНУТИ









ZRÓB TO SAM
SCRATCHBUILD
AM MEISTEN ZU MACHEN
FAIRE LE PLUS
RENDITI
TEE ITSE
GÖR DIG SJÄLV
ЗРОБИТИ САМОЮ

PARTS




H x2





Decal Sheet




PE Parts (M-269) Photo-etched parts









15




16




17




19




18




20







21





22







25



26




A



! H5 don't use for transport position (without wings)


B




for transport position (without wing)

H15


27




R



L



R



PE14 (PE12)

PE13

Ga5

PE12

H6

PE18

26

A20

PE1

04

H8

L

cut for transport position
(without wings)

H1

28

H9

R

H10

C5

C3

R

C1

29

H4

cut for transport position
(without wings)

H1

H10

L

H9

C6

C2

L

C4

H4

L28

R

30

R

Ha3

Ha3

Ha1

Ga2

Ga3

Ga6

Ga4

Ga1

30

31

x2 PE24

27


L

Ha4

Ha4

Ha2

2 K-SALB Aero O/Y, Finland, Mid 1920's



VOLODYMYR BOOTH 2025

3 T-DKOV Dansk Lufttransport, Mid 1920's

